

# PARK WOOD REGENERATION SCHEME PROGRESS PHOTO'S 19<sup>th</sup> JAN 06



Demolished site of Wellington House



Site Hoarding erected along Bell Road



Nagpur House, Partially demolished



Nagpur House



Nagpur House

Site set up of Phase 1 complete, Hoarding erected etc., Calcutta House, New Dehli House and Wellington House demolished. Demolition of Nagpur House in progress.

Demolition phase and site clearance due to be complete mid February